

Welding Leather Hood

Elevate your welding experience to a new level of safety and comfort with the KasWeld Welding Leather Hood. Meticulously engineered with your protection in mind, this hood is your steadfast defence against the intense conditions of welding operations.

Crafted from the highest quality premium leather, the KasWeld Welding Leather Hood forms an impenetrable barrier against sparks, spatter, and heat. Its ergonomic design ensures a seamless fit, allowing you to work unrestricted and confidently. The adjustable headband guarantees a snug yet comfortable feel for prolonged tasks.

Equipped with a convenient flip-up lens holder, this hood accommodates a variety of welding lenses, offering unobstructed visibility while safeguarding your eyes from harmful light emissions. Whether you're tackling MIG, TIG, or arc welding, the KasWeld Hood stands ready.

This welding hood is not only a protector but a partner in performance. Its rugged construction endures the harshest environments, making it an indispensable tool for professionals and enthusiasts. The universal size and timeless dark brown shade make it a versatile choice.

Technical Specification:

Item Name:	Welding Leather Hood
Brand:	Kasweld
Product Category:	Safety
Material:	Premium Leather
Headband:	Adjustable
Lens Holder:	Flip-Up
Suitable for:	Various Welding Processes
Color:	Yellow
Compatibility:	Standard Welding Lenses
Durability:	Rugged Build
Color:	Clear
Size:	Universal



Insulation:

The KasWeld Welding Leather Hood offers exceptional insulation against sparks, radiant heat, and molten metal splatter. The premium leather material is a barrier, preventing these potential hazards from reaching your skin and clothing. This insulation property ensures your safety and comfort, allowing you to focus on your welding tasks without any worries.

Safety Precautions:

1. Always ensure the hood is worn properly and securely fastened before starting any welding operation.
2. Regularly inspect the hood for signs of wear and tear. Replace it immediately if any damage is detected.
3. Use appropriate safety gear, including eye protection, flame-resistant clothing, and the welding hood.
4. Keep the hood clean and free from flammable materials to prevent fire hazards.
5. Store the hood in a cool, dry place away from direct sunlight and heat sources.
6. Avoid exposing the hood to chemicals or solvents that might degrade its protective qualities.
7. Only use compatible standard welding lenses with the flip-up lens holder.
8. Before welding, ensure the lens is properly positioned and secured to maintain clear vision.

Disclaimer:

The KasWeld Welding Leather Hood is designed to protect against welding-related hazards effectively. However, following proper safety practices and using additional safety gear as necessary is essential. The manufacturer shall not be liable for any accidents, injuries, or damages that may occur due to improper use or negligence. The user assumes all responsibility for the appropriate use and maintenance of the welding hood.

Our Locations

China

No.3, Fuan Huayuan,
Pingdu, Qingdao, China

USA

17599, Paxton Ave Lansing,
Illinois 60438 – USA

India

No.104, 1st Floor, Premier
Presidency, Langford Road,
Bengaluru 560025